

Menu

HISTORY FILE MAP for year 2008

REAL TIME


PLAYBACK

RECALLED REALTIME

RECALLED PLAYBACK

121.05:05-06:30 85m of realtime data loss plus 4h 40m of playback loss due to antenna stowing at DSS-14 caused by strong winds (in excess of 45mph). Data recorded during the period 121.00:25-05:05 was lost during the playback. DR G108567 refers.

121.09:50-10:45 55m of realtime data loss plus 55m of playback loss due to antenna maser failure at DSS-14. Data recorded during periods 121.06:30-08:50 and 120.22:52-121.00:25 was lost during playback. DR G108569 refers.



125.05:45-06:25 40m of realtime data loss plus 2h 0min of playback loss due to complex wide power failure at Madrid. Data recorded during the period 125.03:45-05:45 was lost during the playback. DSS-14 used for commanding with 15m of realtime data and 1hr of playback data received over DSS-14. DR M104819 refers.

125.06:38-09:38 2h 50m of realtime data loss plus 10h 36m of playback loss due to complex wide power failure at Madrid. Data recorded during the period 124.16:11-02:47 was lost during the playback. DR M104819 refers.

Data still on DSU